Oil Field Environmental Incident Summary

Responsible Party: WHITING OIL AND GAS CORPORATION **Well Operator:** WHITING OIL AND GAS CORPORATION

Well Name: PHOVDE 8-20 SWD

Field Name: TRUAX Well File #: 90284

Date Incident: 1/15/2016 Time Incident: 00:00 Facility ID Number:

County: WILLIAMS Twp: 154 Rng: 98 Sec: 20 Qtr: NE SE

Location Description:

Submitted By: Corissa Zimmer Received By:

Contact Person: Corissa Zimmer

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	10	Barrels	10	Barrels	10	barrels	
Brine	745	Barrels	730	Barrels	730	barrels	
Other	15	Barrels	15	Barrels	15	barrels	

Description of Other Released Contaminant:

Melted snow (freshwater)

Inspected: Written Report Received: 7/8/2016 Clean Up Concluded: 6/21/2016

Risk Evaluation:
None noted.

Areal Extent:

Potential Environmental Impacts:

None noted.

Action Taken or Planned:

All released material has been contained on location in lined berms; no material was released off location. Upon discovery during routine nighttime inspections, Whiting personnel immediately shut in the facility and dispatched company and third party personnel and equipment to remove all released liquids. Whiting utilized vacuum trucks to effect removal of the released material and expects to have all material removed from the location. Whiting is continuing to remove material and investigate the cause of the release.

Wastes Disposal Location: Any removed solid materials will be sent to Secure Disposal, and, as of 14:00, all liquids are being sent to the P Evitt SWD.

Agencies Involved:

Updates

Date: 1/19/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, all of the released materials were contained within a lined diking system. NDIC retains oversight.